

ANNUAL SURVEYS.

2445

Rec 4/6/61

In No. 771 Survey held at Sunderland Date 8th May 1861
 on the S.S. "Byhope" Master J. Douglass
 Tonnage 475 Built at Sunderland When built 1860
 By whom built James Laing Owners Hugh Taylor
 Port belonging to London Destined Voyage London
 If Surveyed Afloat or in Dry Dock South Graving Dock

Last Survey, No. 6964 Port of Sunderland August/60 Classed GA1
 1860

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>Sufficient</u>
Waterways <u>"</u>	Breasthooks and Stemson	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>Good</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>"</u> When put on <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen?

This keel has been on shore damaged one plate & started several rivets and caulking which has now been efficiently repaired and is now in good condition eligible in my opinion eligible to remain as classed GA1

Committee's Minute 11th June 1861

Character assigned GA1

Edwin R. Buchanan

1801435-0059