

2909

1745

REPORT of SURVEY for REPAIRS.

No. 1745 Survey held at Liverpool Date 19th August 1862
 on the Iron Ship Robinson Master Eller
 Tonnage 889 Built at Belfast When built 1859
 By whom built Hickson Owners R Hickson
 Port belonging to Liverpool Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock Dry Dock and afloat

Last Survey, No. 2417 Port Iron Classed 12 A 1
 REPAIRS The bottom scraped and coated with Paint, Plating joints good

Present Condition of the

Decks	<u>good</u>	Trunnions	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	<u>good</u>	Breasthooks and Stems	<u>good</u>	Pumps	<u>"</u>
Comings	<u>good</u>	Transoms, Pointers, and Crutches	<u>good</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>good</u>	Timbers of the Frame	<u>good</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>good</u>	Keelsons	<u>good</u>	Sails	<u>well found</u>
Plank sheers	<u>Iron</u>	Clamps and Shells	<u>good</u>	Anchors	No. of <u>3 Bows / 2 Heavy</u>
Sheerstrakes	<u>Iron</u>	Ceiling	<u>good</u>	Cables	<u>"</u>
Topsides	<u>Iron</u>	Rudder	<u>good</u>	Hawsers and Warps	<u>all good</u>
Wales	<u>Iron</u>	Copper	<u>When put on</u>	Standing & Running Rigging	<u>"</u>
Plank (Bottom) and Counter	<u>Iron</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. all satisfactory where seen

Is now in a fit and efficient state for the safe conveyance of
dry and perishable cargoes to and from all parts of the world and in
my opinion should retain her present character

The Amount of Fee.....£ " : " : " is received by me

Special..... / : / : 0 22/9/62

Certificate (if required) " : " : "

Committee's Minute 26th September 1862Character assigned 12 A 1

© 2019

Lloyd's Register
Foundation

IRON436-0038

"Belington" 1774³



© 2019

Lloyd's Register
Foundation