

2937

2825

REPORT of SURVEY for REPAIRS.

No. 2823 Survey held at Newcastle Date 15 Sept to 10 Oct 1862
 on the S.S. "Springmorton" Master C. Douglas
 Tonnage 986 Built at Newcastle When built 1850
 By whom built Colin Bruce Owners Long & Co
 Port belonging to Newcastle Destined Voyage Newcastle
 Is Surveyed Afloat or in Dry Dock off Mill-Palmer & Co's Quay, Newcastle

Last Survey, No. 2912 Port Newcastle Classed 6th 1st

REPAIRS of Damage by collision with the S.S. Lady Alice Lambton, which vessel is seen to have jammed. Damages on the Starboard side plates between the Light & Main and Main & Foremast frames scapheel, with angles in lengths from 8 to 10 feet. About 250 rivets besides those in the new work, and 60 to 65 feet of caulking made good.

Present Condition of the

Decks	Tree-nails	Windlass and Capstan
Waterways	Breasthooks and Stemson <u>where</u>	Pumps
Comings	Transoms, Poiners, and Crutches <u>same</u>	Boats
Upper Deck Beams & Fastenings <u>same</u>	Timbers of the Frame	Masts, Yards, &c. <u>complete</u>
Lower Deck Beams & Fastenings	Keelsons <u>good</u>	Sails
Plank-sheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Apparently good

This vessel appears now in good condition, and in my opinion eligible to be re-rated as classed A.

The Amount of Fee.....£ 2: - - is received by me,

Special Damage £: £: -

Certificate (if required) - - -

Committee's Minute 24th October 18 62Character assigned 621second damage repair

© 2019

Lloyd's Register
Foundation

IRON436-0067