

REPORT of SURVEY for REPAIRS.

Rec 5/3/63

No. 18057 Survey held at Liverpool Date 1th Feb^y 18 63
 on the Iron Screw Steamer Grecian Master Thomson
 Tonnage 1854 Built at Belfast When built 1861
 By whom built Harland Owners Bobby Ward
 Port belonging to Liverpool Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 2593 Port Liverpool Classed 12 A 1

REPAIRS The bottom scraped and coated with Paint
Plating & rivets good

Present Condition of the

| | | |
|-------------------------------|--------------------------------------|----------------------------|
| Decks | Freemasts | Windlass and Capstan |
| Waterways | Breasthooks and Stems | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | Sails |
| Plank sheers | Keelsons | Anchors |
| Sheerstrakes | Clamps and Shells | Cables |
| Topsides | Ceiling | Hawsers and Warps |
| Wales | Rudder | Standing & Running Rigging |
| Plank (Bottom) and Counter | Copper | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. All satisfactory when seen

Is now in a fit and efficient state for the safe conveyance
of dry and perishable cargoes to and from all parts of the world and in
my opinion should retain her present character

The Amount of Fee.....£ : : is received by me,

Special..... / : / : 0 2/3/63 Blm

Certificate (if required) : 5 : "

Committee's Minute 6th & March 18 63

Character assigned 12 1/2



© 2019

Lloyd's Register Foundation

IRON436-0148

"Grecian" 1805



© 2019

Lloyd's Register
Foundation