

REPORT of SURVEY for REPAIRS.

Rev 6/8/63

No. 7276 Survey held at Sunderland Date 31st July 1863
 on the Ship Albion House Master _____
 No 199 Tonnage 365 Built at Hartlepool When built 1850
 int^l Reg. By whom built _____ Owners R. Young
 Port belonging to Wishich Destined Voyage to China
 If Surveyed Afloat or in Dry Dock Austins M^o

Last Survey, No. 2269 June Port Hartlepool Classed 12A1
 50.

REPAIRS

Found this vessel hauled up for the purpose of painting the bottom, which was being done without the corrosion being cleaned off of which there was a considerable quantity. I met the agent of the owners on board and informed him that it was requisite that a survey be held on the ship in accordance with the rules section of in order to retain her class, and noted the same to him in writing, but the survey was declined, and the vessel since removed from the ship.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

The ship not having been surveyed since the date of her build (though seen under similar circumstances in London about two years since by Mr. Light (see his report) & being to leave her class in the hands of the Committee.

The Amount of Fee.....£ - : - : is received by me,

Special..... - : - : -

Certificate (if required) - : - : -

Committee's Minute

7th August 1863

Character assigned



Deposited
 by
 6/8/63
 Foundry

IRON 436-0431