

3429

REPORT of SURVEY for REPAIRS.

No. 3431 Survey held at Hull Date 26th Decem^r 1863
on the Iron Schooner "Albion" Master R Souleby
Tonnage 900 Built at Hull When built 1861
By whom built M Sammlson Owners Wilson &c
Port belonging to Hull Destined Voyage Dantzic
If Surveyed Afloat or in Dry Dock In Humphreys dry dock

Last Survey, No. 3078 Port Iron. Classed GA 1
(2.5.62) 63

REPAIRS

Now done Docted on account of having been on shore
and leaking

On examination found one of the blow off pipes
under bottom disturbed and several of the batts strained.
the batts caulked where required & Blow off made
perfect. Bottom coated with tar & the upper plating
with one coat of paint

Present Condition of the

Decks	<u>Good</u>	Freemasts <u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>Good</u>	Breasthooks and Stemson	Pumps	<u>Good</u>
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto Ditto at other places	Sails	<u>Good</u>
Planksheers	<u>Good</u>	Keelsons	Anchors No. of	<u>Good</u>
Sheerstrakes	<u>Good</u>	Clamps and Shelves	Cables	<u>Good</u>
Topsides	<u>Good</u>	Ceiling	Hawsers and Warps	<u>Good</u>
Wales	<u>Good</u>	Rudder	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	<u>Good</u>	Copper When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

Is eligible in my opinion to remain as classed GA 1

The Amount of Fee.....£ — : — : is received by me,

Special.....£ : £ : —

Certificate (if required) — : — : —

Committee's Minute 1st January 18 64

Character assigned GA 1



© 2019

Lloyd's Register
Foundation

IRON437-0096