

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 9399** Survey held at South Shields Date 18 June to 18 July 1864
 on the Iron Steamer "Aurora" Master Mitchell
 Tonnage 698 Built at Newcastle When built 1863
 By whom built Palmer Bros & Co Owners Pickernell Bros
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock at Gropes dry Dock

Last Survey, No. 3237 Port New Shields Classified 9 A 1
63

REPAIRS

Through damage sustained through having been on shore
 17 pieces of angle iron at outside of Tank connecting side of Tank
 to floor plates renewed. 8 plates of Tank top removed & rivetted
 about 400 rivets in fore and aft angle iron at lower edge of vertical
 side of Tank side, bulks of outside plating and in frames
 renewed - also 80 rivets in keel edge of garboard strake -
 Stow beams reset. bulks of outside plating recaulked & the
 bottom recaulked
 Not of damage. bulks recaulked -

Present Condition of the

Decks	} <u>Good</u>	Greenails <u>Rivets part new</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stems		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frames at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>Good</u>	Ditto Ditto at other places	} <u>Good</u>	Sails	} <u>Good</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Stowage	} <u>Good</u>	Rudder	} <u>Good</u>	Standing & Running Rigging	
Plank (Bottom) and Counter		Copper		When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

This Vessel is now in good condition and eligible to
 continue as Classed A 1

Wm L. Davey

Amount of Fee.....£ 2 : - : - is received by me,

Special or Damages 3 : 3 : -

Certificate (if required)

Committee's Minute

Fracter assigned

Record damage repair



© 2019

Lloyd's Register
Foundation

IRON437A-0122