

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 3187** Survey held at **Dunkeithing** Date **1st August** 18**64**
 on the **Iron Screw Steamer "Union"** Master **W. Struck**
 Tonnage **420** Built at **Dunkeithing** When built **1864**
 By whom built **John Scott** Owners **W. & C. J.**
 Port belonging to **Lubeck** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Afloat in Harbour**

Last Survey, No. **3681** Port **Iron** Classed **A. 1.**
 6 64

REPAIRS

Present Condition of the

Decks In good condition	Rivets In good condition	Windlass and Capstan W. Good & Sufficient
Waterways "	Breasthooks and Stenion "	Pumps "
Tomings "	Transoms, Pointers, and Crutches "	Boats 3 "
Upper Deck Beams & Fastenings "	Timbers of the Frames at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Sails "
Plank sheers "	Keelsons "	Anchors No. of 3 B 10 2 10 "
Heerstrakes "	Clamps and Shelves "	Cables 210 fathoms "
Oppsides "	Ceiling "	Hawsers and Warps "
Stales "	Rudder "	Standing & Running Rigging "
Eng (Bottom) and Counter "	Copper When put on "	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. **Good**

This vessel is in good and efficient condition eligible in my opinion to remain as Classed A. 1.

The Amount of Fee.....£ : : is received by me.

Special..... : :

Certificate (if required) **0 : 5 : 0**

Committee's Minutes **5th August** 18**64**

Character assigned **A. 1.**



© 2019

Lloyd's Register

IRON 37A-0125