

3702

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No. 2733

Survey held at

Bristol

Date

12 August

18

64

on the

Brig Mosquito

Master

Richard Miller

Tonnage

198

Built at

Purpura

When built

1859

By whom built

Henderson

Owners

Gamble

Port belonging to

Spool

Destined Voyage

Bristol to South America

If Surveyed Afloat or in Dry Dock

dry dock

Last Survey, No.

3203

Port

Bristol

Classed

9th Iron

(2.5.61)

63

REPAIRS

This vessel has been docked and the outside plating scraped clean. All the sparring removed inside both sides, and the plating scraped. Had some of the Biting in flat removed each side and the Cement and Asphalt found in good condition and adhering to the plating.

Bottom now coated with Red Lead, and two coats of patent composition; and the inside plating coated above Bilges with Cement.

She is now in good condition.

Present Condition of the

Decks	Good	Decayed	Plants	Good	Windlass and Capstan	Good
Waterways	do		Breasthooks and Stemson	do	Pumps	two do
Comings	do		Transoms, Pointers, and Crutches	do	Boats	two do
Upper Deck Beams & Fastenings	do		Timbers of the Frames at the openings	do	Masts, Yards, &c.	do
Lower Deck Beams & Fastenings	do		Ditto Ditto at other places	do	Sails	well found do
Planksheers	do		Keelsons	do	Anchors	No. of 313, 18 lb Wedge
Sheerstrakes	plating do		Clamps and Shelves	do	Cables	Complete
Topsides	do do		Ceiling	do	Hawsers and Warps	sufficient
Wales	do do		Rudder	do	Standing & Running Rigging	good
Plank (Bottom) and Counter	plating do		Copper	When put on Aug 1864		
General Observations and Opinion,			Caulking of Bottom, Deck, & Waterways.	good		

This vessel being in good condition, I am of opinion she may now be classed as triennially surveyed.

The Amount of Fee.....£ : : is received by me,

Special.....2 : :

X Certificate (if required) : 2 : 6

Committee's Minute

16 August

18 64

Character assigned

B 1

MT (S. S. 64)



© 2019

Lloyd's Register
Foundation

IRON 437A - 0132