

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 6 D. Survey held at London Date August 24th 1864
 on the S. "Nelson" (Iron) Master Charles Cobb
 Tonnage 1240 Built at Glasgow When built 1862
 By whom built _____ Owners British Shipowning Company
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Union Dry Dock.

Last Survey, No. 3162 Port Iron Classed 12. A. I.
 REPAIRS now done: 5.03.

The bottom cleaned and painted with Gray's Composition.

Present Condition of the

Decks <u>Good where seen</u>	Timber <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Ends of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>Sufficient</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen.

This Vessel appears to be in good & efficient condition, and is eligible, in my opinion, to remain as classed.

The Amount of Fee.....£ _____ is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : 5 : -

Committee's Minute 6th January 18 65

Character assigned 1271



© 2019

Lloyd's Register Foundation

IRON438-0088