

3943  
Iron

26525

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 652 No. 3943 Survey held at London Date Jan 24<sup>th</sup> 1865  
 on the Ship "City of Quebec" Master J. Downie  
 Tonnage 564 Built at Greenock When built 1833  
 By whom built \_\_\_\_\_ Owners Montgomery  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock East India Dock

New 30/1/65

Last Survey, No. 3943 Port Iron Classed 12 A 1/4  
 L. S. 63-

REPAIRS  
 How done, eight planks of deck on the Starboard and ten aft, on the Port side - two in midships and eight aft - renewed with yellow pine - the Crummings and a portion of the upper deck Caulked -

Present Condition of the

Decks <u>Port - new &amp; Caulked</u>	Treenails <u>None</u>	Windlass and Capstan _____
Waterways <u>Good</u>	Breasthooks and Stemson _____	Pumps _____
Comings <u>a</u>	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places _____	Sails <u>Sufficient -</u>
Planksheers _____	Keelsons <u>Good when</u>	Anchors No. of _____
Beerstrakes <u>Good</u>	Clamps and Shelves <u>seen</u>	Cables _____
Upsides _____	Ceiling _____	Hawsers and Warps _____
Stales _____	Rudder _____	Standing & Running Rigging _____
Hulk (Bottom) and Counter <u>Good</u>	Copper <u>None</u> When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good  
 I am of opinion that she is now in good and efficient condition, and fit to remain as classed 12 A 1/4.

*B. W. Raymond*

The Amount of Fee.....£ 2 : 0 : \_\_\_\_\_ is received by me,  
 Special..... 1 : 1 : \_\_\_\_\_  
 Certificate (if required) : 5 : \_\_\_\_\_

Committee's Minute 31<sup>st</sup> January 1865

Character assigned 12 A 1/4 second class

