

4252

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **22** No. **19579** Survey held at **Liverpool** Date **9 and 11 August 1865**  
 on the **Iron Steamer Palikari** Master  
 Tonnage **1116** Built at **Stockton** When built **1860**  
 By whom built Owners **H. T. Lifford**  
 Port belonging to **Liverpool** Destined Voyage **Sir. Smyrna**  
 If Surveyed Afloat or in Dry Dock **Under Repairing Dock**

Last Survey, No. **3076** Port **Iron Ship** Classed **PA**  
**REPAIRS** **263**

Finding this vessel in dry dock, having her bottom painted. Wrote to the Owners respecting the triennial survey but on my visit - on the 12<sup>th</sup> I found no steps had been taken for such examination and she was then about to be taken out of dock.

A number of the butts in the bilges and flat of bottom are much wasted away by repeated caulking and leakage occurs in several of these places.

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. Condition, how ascertained.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

As this vessel should have been submitted to survey and I have had no opportunity of ascertaining her condition inside. I beg to leave the question of retaining her class to

The Amount of Fee.....£ : : is received by me, the decision of the  
 Special..... : : Committee  
 Certificate (if required) : :

Committee's Minute **Liverpool 18<sup>th</sup> August 1865**  
 and Comre **22 August 1865**

Character assigned **Expense Character**

IRON/438-0401

Notice to owner

Refd to Special Committee

24<sup>th</sup> Sept. 1865



"Palisado"  
- 19519 -



© 2019

Lloyd's Register  
Foundation