

4253

REPORT of SURVEY for REPAIRS.

Survey held at London Date Augt 25th 1865.
 Crew Stm^r Palikari Master E. Hairby

Built at Stockton When built 1860.
Richardson Owners H. Lafone.
Liverpool Destined Voyage Constantinople.
 or in Dry Dock Afloat.

Survey Report

4253

Port Iron.

Classed

Called this morn^g on board, found them discharging
 of Coals. was informed it was not intended to dock her
 present, but that they were about loading for Constantinople.
 The Master not being on board, Left Notice Card. - the following
 is a Copy.

Copy

Sir

According to my instructions, having this
 day been on board the Iron Steamer Palikari
 now lying afloat unloading in the London docks,
 referring to the Liverpool Report correspondence with
 the Owner &c, it will be necessary to put her into dry
 dock, high on blocks, lift the Ceiling Planks, and
 expose the inner and outer surfaces of the plating
 and efficiently repair her, as recommended. Hence
 she is reported to the Committee to be clapped in the
 Register Book.

To Captain E. Hairby
 Iron Steamer Palikari
 1116 tons

I am Sir

Your obedient servant

Samuel Presons

11 August 25-1865.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. Condition, how ascertained.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 18

Character assigned



© 2019

Lloyd's Register
Foundation

IRON438-0403