

on Ships

# ANNUAL SURVEYS.

27051

No.            Survey held at London Date July 13<sup>th</sup> 1865  
 on the Steamer "Alexandra" Master W. Russell  
 Tonnage 813 Built at London When built 1863  
 By whom built Thames Iron Works Owners Lon. Ital. & Adc. S. N. Co.  
 Port belonging to London Destined Voyage Lon & Mediterranean  
 If Surveyed Afloat or in Dry Dock Dorsifery Dry Dock

Recd 2/10/65

Last Survey, No. 3241 Port of Iron Classed 9 A.1.  
 8.63

ent Condition of the

ys	} good	Ironails Rivets	} good	Windlass and Capstan	} good
		Breasthooks and Stimson		Pumps	
ck Beams & Fastenings	} where	Transoms, Pointers, and Crutches	} where	Boats	} and
		Timbers of the Frame at the Openings		Masts, Yards, &c.	
ck Beams & Fastenings	} seen	Do Do at other places	} seen	Sails	} sufficient
rs		Keelsons		Anchors No. of	
es	} Painted	Clamps and Shelves	} seen	Cables	} where
		Ceiling		Hawsers and Warps	
		Rudder		Standing & Running Rigging	seen
tom) and Counter		Copper Paint When put on <u>now</u>			

Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

done. The bottom scraped and painted - She is now in  
 good and efficient condition fit in my opinion to remain

Minute 6<sup>th</sup> October 1865  
 assigned 9 A.1

as classed 9 A.1.

Hornish  
 Certificate (if required)

No.            Survey held at London Date Sep 5<sup>th</sup> & 28<sup>th</sup> 1865  
 on the Ship "Himalaya" Master C. B. Low  
 Tonnage 1008 Built at Sunderland When built 1863  
 By whom built Pile Owners G. D. Tyer  
 Port belonging to London Destined Voyage New Zealand & India  
 If Surveyed Afloat or in Dry Dock Youngs Dry Dock & East India Dock

Last Survey, No. 3445 Port of Iron Classed A.1.  
 1263

resent Condition of the

ways	} good	Ironails Rivets	} good	Windlass and Capstan	} good
		Breasthooks and Stimson		Pumps	
gs	} where	Transoms, Pointers, and Crutches	} where	Boats	} and
Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
r Deck Beams & Fastenings	} seen	Do Do at other places	} seen	Sails	} efficient
ksheers		Keelsons		Anchors No. of	
rstrakes	} 2	Clamps and Shelves	} seen	Cables	} where
sides		Ceiling		Hawsers and Warps	
es		Rudder		Standing & Running Rigging	seen
le (Bottom) and Counter		Copper Paint When put on <u>now</u>			

eral Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

now done, The bottom scraped and painted with white Zinc -  
 to ceiling lifted from the bilge keelson to bilge keelson and the  
 otton re-cemented with Portland Cement - and all the inside  
 orke cleaned and painted - She is now in good condition, fit

Committee's Minute 6<sup>th</sup> October 1865  
 Character assigned A.1

Hornish  
 Certificate (if required)