

REPORT of SURVEY for REPAIRS.

No. in Book. **No.** 6 Survey held at London Date Oct^r 6th 1865,
on the Iron Screw Ste^r Fairfax. Master J. Young
Tonnage 555 Built at Glasgow. When built 1865.
By whom built 437 Owners G^e. I. Screw Col^r. Comp^y
Port belonging to London Destined Voyage St^a Nazaire
If Surveyed Afloat or in Dry Dock "Lower Globe"

ast Survey, No. 4179 Port St^a Nazaire Classed A. 1.
7. 65

REPAIRS

Lifted some Ceiling planks in the lower Hold. put in a rivet in lieu of one found started or broken. Caulkd some butts found leaky. Caulkd the deck. Paid the bottom with black Varnish.

Present Condition of the

Decks	<u>in good order</u>	Freeboards <u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained.	<u>from the deck</u>
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchor No. of <u>3</u>	"
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder <u>efficient</u>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>When put on</u>	Standing & Running Rigging	"
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good</u>				

I am of opinion she is entitled to remain as class'd A. 1.


The Amount of Fee.....£ 1 : 1 : 0 is received by me,
Special..... 1 : 1 : 0

Samuel Wilson.

Certificate (if required)

Committee's Minute 2nd December 18 65

Character assigned A 1



© 2019
Lloyd's Register
Foundation
IRON 439-0042