

REPORT of SURVEY for REPAIRS.

Date 20/1/66

No. in Reg. Book. **No. 19732** Survey held at **Birkenhead** Date **Dec^r 28/55** Jan^y 5 1866
 on the **Iron B^o "Recife"** Master **Douglas**
 Tonnage **465** Built at **Belfast** When built **1862 - 10 mo**
 By whom built **Harland** Owners **J. Napier**
 Port belonging to **Liverpool** Destined Voyage **South America**
 If Surveyed Afloat or in Dry Dock **Clayton's Woodside graving dock.**

Last Survey, No. **2996** Port **Shore** Classed **12 A 1**

REPAIRS now done for the (t. s.) Survey. 3 strokes of cutting on both sides for flat of bottom taken up. and the Cement and iron where it could be seen fully examined and found good. Scraped and painted on the inside and the bottom painted below the load water-mark. Rudder repaired in upper pintle.

Present Condition of the

Decks good	Treenails	Windlass and Capstan good
Waterways "	Breasthooks and Stemson	Pumps "
Comings "	Transoms, Pointers, and Crutches	Boats good and sufficient
Upper Deck Beams & Fastenings Iron	Timbers of the Frame at the openings Iron	Masts, Yards, &c. "
Lower Deck Beams & Fastenings good	Ditto Ditto at other places good	Condition, how ascertained as seen from the deck
Planksheers where	Keelsons where	Sails good and complete
Sheerstrakes seen	Clamps and Shelves seen	Anchors No. of good 3 B. 15. 24.
Topsides	Ceiling	Cables good and complete
Wales	Rudder	Hawsers and Warps "
Plank (Bottom) and Counter painted	Copper When put on	Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. **good where seen.**

This vessel is now in good condition and having been surveyed in accordance with the Rule Sec^t 17 and found good she is eligible to be marked (t. s.) 1866. and remain as Classed 12 A 1.

The Amount of Fee.....£ " : " : " is received by me,

Special..... 3 : 3 : 0 17/1/66

Certificate (if required) " : 5 : "

Committee's Minute **Liverpool 19th January, 1866**

Character assigned **12 A 1**

SR (t. s. - 66)

REPORT OF SENATE JO. BERRYMAN

"Precise" 19754



© 2019
Lloyd's Register
Foundation