

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **282** No. **25399** Survey held at Birkenhead & Liverpool Date March 25-1867 *Ry 3/2/77*
 on the (Son) S.S. "Volunteer" Master J. Wilson
 Tonnage 671 Built at Newcastle When built 1862
 By whom built Marshall Owners J. Laing
 Port belonging to Sunderland Destined Voyage London
 If Surveyed Afloat or in Dry Dock Great Heath Graving & Victoria docks

Last Survey, No. — Port — Classed 2A
88 65-65

REPAIRS Through Damage

Two plates renewed in 2nd shake down from the Sheer stake - abreast of Foremast Port side - & long covering pieces of angle iron fitted & rivetted to two frames - where partly broken.

The Bottom Scraped & coated with Composition.

Not now found in Register book
2/2/77
J.F.Z.

Present Condition of the

Decks <u>Good</u>	<u>Ironails rivets</u> <u>Good</u>	Windlass and Capstan
Waterways <u>"</u>	Breasthooks and Stemson	Pumps <u>Good</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places	Condition, how ascertained <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Upsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Sufficient</u>
Stales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plates <u>"</u>	Copper <u>—</u> When put on <u>—</u>	Standing & Running Rigging <u>"</u>
Bottom (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Satisfactory

I am now in an efficient condition & in my opinion eligible to remain as classed.

The Amount of Fee.....£ 2 : " : " is received by me,

Special..... 1 : 1 : "

Certificate (if required) : :

Committee's Minute Liverpool Feb 2-1877

Character assigned Record only

as not paid, transmit Report to London.

M.L.C.

E. C. Wheeler


© 2019

Lloyd's Register Foundation

IRON439-0170