

REPORT of SURVEY for REPAIRS.

496 No. Survey held at London Date Dec 4th 14th Feb 1866
 on the S. S. "Pyhope" (Shore) Master
 Tonnage 475 Built at Sunderland When built 1860
 By whom built Saing Owners H. Taylor
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Afloat + Pontoon Victoria Dock

Last Survey, No. 3395 Port Shore Classed G A 1
 63

REPAIRS

In consequence of damage see special report:
 three fore hood plates renewed and head repaired.

The outside and inside plating cleaned the ceiling lifted
 and tank lids the bottom inside examined as far as practicable
 and found good — outside painted with two coats of Red Lead.

Present Condition of the

Decks	Treenails	Rivets	Windlass and Capstan
Waterways	Breasthooks and Stemson		Pumps
Comings	Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings	Timbers of the Frame		Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Good where seen	Sails
Planksheers	Clamps and Shelves		Anchors No. of
Sheerstrakes	Ceiling		Cables
Topsides	Rudder		Hawsers and Warps
Wales	Copper	When put on	Standing & Running Rigging
Plank (Bottom) and Counter			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now in good and efficient condition
 and is eligible in my opinion to remain classed
G A 1

The Amount of Fee.....£ 1 : — : — is received by me,

Special..... 2 : 2 : —

Certificate (if required) : : —

Committee's Minute 23rd February 1866

Character assigned G A 1
 (1866)
 record damage repairs

and be marked
 T.S. 1866

Thos. M. Wain



© 2019

Lloyd's Register
 Foundation

IRON439-0197