

4640

Rev 27/3/66

REPAIRS

The following now renewed. - Fifteen Hard Wood Stantions, the Lace piece with Knee and Knight-heads new cemented in flat with Portland Cement. Coated above with two coats of Red Lead, and outside with two coats of paint. Ceiling in Hold 22 thick of American Elm and Red Pine. Rudder Hangings new. Stinclass stripped and unshipped. A Deck House fitted on Deck. Cables ranged and found sufficient. Deck and Waterway caulked.

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

~~Plating~~
Plank (Bottom) and Counter

Rivets
Trenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

~~Timbers of the Frames at the openings~~

Ditto

Keelsons

Clamps and Shelves

Ceiling

Rudder

~~Copper~~

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps 3

Boats 2

Masts, Yards, &c.

Condition, how ascertained

Sails L. D.

Anchors No. of 3 B. 12. 14

Cables 180 fathoms

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion.

The requirements of the Rules Survey N^o 3 for Iron Ships have now been fully complied with, the several parts were seen examined and found good, and in a very satisfactory condition and we respectfully recommend the Owners request that this vessel may be placed on the A. 1. grade to the favorable consideration of the Committee

The Amount of Fee.....£ 3 : 0 : 0 is received by me,

Special..... 4 : 4 : 0

Certificate (if required) 0 : 5 : 0

Committee's Minute 29th March 1866

Character assigned

1 (S. S. 116 = No 3)

Lawrence Bouckman

J. D. Aulinger
© 2019
Lloyd's Foundation

Lloyd's Register
Foundation

IRON 439 - 0266