

# REPORT of SURVEY for REPAIRS.

Rec 3/5/66

No. in Reg. Book. **No. 3648** Survey held at **Aull** Date **27<sup>th</sup> April 1866**  
**97** on the **Hon Sec Sp Viceroy** Master **R Leighton**  
 Tonnage **723** Built at **Sunderland** When built **1862**  
 By whom built **Oswald** Owners **See & Co**  
 Port belonging to **Aull** Destined Voyage **Cronstadt**  
 If Surveyed Afloat or in Dry Dock **When "C" W. Earle slip way & afloat in Green Dock**

Last Survey, No. **4589** Port **I. Ships** Classed **9 A 1**  
 REPAIRS **See Report No 3617** — "Vessel bottom cleaned and coated with tar" now done — The ceiling left in accordance with the rules and the vessel scraped bright from the light water — marks upwards also inside where practicable and recoated with paint —

## Present Condition of the

Decks	<i>Good when seen</i>	Greenails <i>Rivets</i>	<i>Good when seen</i>	Windlass and Capstan	<i>Good sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Coffin When put on		Standing & Running Rigging	

General Observations and Opinion, *Caulking of Bottom, Deck, & Waterways. Efficient*

*Is eligible in my opinion to remain as classed A, and be marked (TS 66)*

The Amount of Fee.....£2: — : is received by me,

Special.....3: 3: —

Certificate (if required) — : — :

Committee's Minute **4<sup>th</sup> May 1866**

Character assigned **9 A 1**

*WMA (TS 66)*



© 2019  
 Lloyd's Register  
 Foundation  
 IRON439-0322