

ANNUAL SURVEYS.

Rec 3/1/66

No. 8832 Survey held at Sunderland Date Augst 23 1866
 on the Iron Screw Admiral Kanaris Master Philpott
 Tonnage 927 Built at Sunderland When built 1858
 By whom built James Laing Owners E Gourley
 Port belonging to Sunderland Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 4762 Port of Liverpool Classed 9 A.L. 3.6.6 (5566)
 The present Condition of the Ribs in the flat of bottom & a little caulking, &c. Bottom Painted & coated outside.

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>2 Br. St & No. 2</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Appears now in an efficient state and in my opinion should remain as classed
Seahouse Martindale

Committee's Minute 4th September 1866

Character assigned

Extra labour £110 received

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____	Port of _____	Classed _____
The present Condition of the		
Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of _____
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways	

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register
 Foundation

IRON 439-0511