

# ANNUAL SURVEYS.

No. 589 Survey held at London Date Sep 22<sup>nd</sup> - Sep 27<sup>th</sup> 1866  
 On the Iron Ship "Tantallon Castle" Master W. Pole  
 Tonnage 1057 Built at Greenock When built 1865 - 3mo  
 By whom built \_\_\_\_\_ Owners Currie & Co  
 Port belonging to Liverpool Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Wigram's Dry Dock & East India Dock

Last Survey, No. 4488 Port of Iron Classed A. 1.

## The present Condition of the

Decks	} <u>good</u>	Transoms	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats <u>5</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Do Do at other places	} <u>where</u>	Sails	} <u>efficient</u>
Planksheers		Keelsons		Anchors No. of <u>3 B. 1 S. 2 K</u>	
Sheerstrakes	} <u>seen</u>	Clamps and Shelves	} <u>seen</u>	Cables	} <u>seen</u>
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>Painted</u>	Rudder	} <u>now</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper			

## General Observations and Opinion,

## Caulking of Bottom, Deck, and Waterways

good where seen

now done, the bottom painted with two coats of McAlister's Patent - She is in good condition fit in my opinion to remain as classed A. 1.

Committee's Minute 5<sup>th</sup> October 1866

Character assigned A. 1.

Certificate (if required)

No. 889 Survey held at London Date Sep 25<sup>th</sup> - 28<sup>th</sup> 1866  
 On the Iron Ship "Forcyra" Master Goodwin  
 Tonnage 734 Built at Stockton When built 1862 - 7mo  
 By whom built \_\_\_\_\_ Owners Ang. Ionian S. N. Coy.  
 Port belonging to London Destined Voyage Alexandria  
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 4338 Port of Iron Classed 9 A. 1.  
(t.s. 65) 8. 68

## The present Condition of the

Decks	} <u>good</u>	Transoms	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats <u>5</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Do Do at other places	} <u>where</u>	Sails	} <u>seen</u>
Planksheers		Keelsons		Anchors No. of <u>3 B. 1 S. 2 K</u>	
Sheerstrakes	} <u>seen</u>	Clamps and Shelves	} <u>seen</u>	Cables	} <u>seen</u>
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>Painted</u>	Rudder	} <u>now</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper			

## General Observations and Opinion,

## Caulking of Bottom, Deck, and Waterways

good where seen

now done, the bottom scraped and painted with 2 coats of Red lead and one of tallow, the timbers lifted and the floors &c examined and found satisfactory. She is in good condition fit in my opinion to remain as

Committee's Minute 5<sup>th</sup> October 1866

Character assigned 9 A. 1.

Certificate (if required)