

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *382* No. *20251* Survey held at *Liverpool* Date *15th to 31 Oct 1866*
 on the *Iron S. Remchund Roychund* Master *J. Scott*
 Tonnage *1257* Built at *Liverpool* When built *1864 - 11 mo*
 By whom built *Hardy* Owners *Peninsular & Oriental Steam Navigation Co. (no change)*
 Port belonging to *Liverpool* Destined Voyage *India*
 If Surveyed Afloat or in Dry Dock *Brunswick dry dock & Afloat*

Last Survey, No. *4671* Port *Iron.* Classed *A 1*
68-

REPAIRS
 Ceiling of flat lifted and about 100 Tons of Kentledge introduced, between floors and well secured with Portland cement. Every 10th space left free for water
 Outside cleaned and bottom coated with Gibb's patent

Present Condition of the

Decks	Good	Trunnels	Rivets	Windlass and Capstan	Good
Waterways		Breasthooks and Stemson		Pumps	
Rigging	where	Transoms, Pointers, and Crutches	Good	Boats	Good
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	seen	Ditto Ditto at other places	where	Condition, how ascertained	and
Plank sheers		Keelsons		Sails	
Upper strakes	seen	Clamps and Shelves	seen	Anchors No. of	suffr
Sides		Ceiling		Cables	
Planks	seen	Rudder	seen	Hawsers and Warps	
Plank (Bottom) and Counter		Copper		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. *Good*

She appears now in good condition and in my opinion may remain as classed A 1

Will. L. Davey

The Amount of Fee.....£ " : " : " is received by me,

Special..... 1 : 1 : - *1/10/66*

Certificate (if required) " : " : "

Committee's Minute *Liverpool, 6th November, 1866.*

Character assigned *A 1*

OK



© 2019
 Lloyd's Register
 Foundation

"Fennichund
Rogechund"
-20251-



© 2019
Lloyd's Register
Foundation