

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **836** No. **20283** Survey held at **Liverpool** Date **9th to 29th Oct^r 1866**
 on the **Iron Ship Merwarjee Framjee** Master **C. Pike**
 Tonnage **1179** Built at **Pat. Blazon** When built **1863**
 By whom built **J. Reid** Owners **Johnston**
 Port belonging to **Liverpool** Destined Voyage **for Bombay**
 If Surveyed Afloat or in Dry Dock **Sandown Graving and Wet Dock**

Last Survey, No. **4247** Port **Liverpool** Classed **12A1**

REPAIRS

The ceiling in hold up to the biter keelsons on both sides, all fore and aft, lifted, and the cement extended to cover the rivets connecting the floors to the frames. The inner surfaces of the outside plating above the biter scraped and painted. Plating outside scraped and coated. Four scuppers 12x2 cut close above the gunwale angle iron - the others not being sufficient at times to clear the deck of water.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Plank sheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Hulk (Bottom) and Counter	Copper	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

This ship is in good and efficient condition eligible to remain as classed, &c. at the wish of the owner with the approval of the Committee to be classed **A1** and to be

Amount of Fee £ : : : is received by me. Marked S.S. Nos. 66.

Special : : : 23/11/66

Certificate (if required) : : : 5 : :

Committee's Minute **Liverpool, 23rd November, 1866.**

Character assigned **A1 (S.S. Nos. 66.)**

LK



© 2019

Lloyd's Register Foundation

IRON440-0185

"Nerwaryee Tranyjee"
-20283-



© 2019

Lloyd's Register
Foundation