

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 149 Survey held at London Date 9th to 16th Nov. 1866
 on the Iron Screw "The Greek" Master J R Heppells
 Tonnage 447 Built at Stockton When built 1864. (11 mo)
 By whom built Richardson Owners Elliott Thos. S. Peggie
 Port belonging to London Destined Voyage not fixed
 If Surveyed Afloat or in Dry Dock Thames dry dock.

Last Survey, No. 4316 Port Iron. Classed A.1. (9.65.)
 REPAIRS Now done.

The outside scraped from keel to gunwale, several butts in the bottom on each side recaulked, the bottom payed with two coats of red-lead, the topsides with one coat of paint.

Nearly the whole of the timbers lifted, and part of the ceiling amidships on each side, (for the purpose of fitting wood wash boards) and found the cement satisfactory adhering to the outside plating, frames, floors, &c

The upper deck caulked from Poop to Forecastle, and including the Poop and Forecastle decks.

Present Condition of the

Decks <u>upper, caulked,</u>	<u>good</u> <u>where</u> <u>seen</u>	<u>Treenails</u>	<u>good</u> <u>where</u> <u>seen</u>	Windlass and Capstan	<u>good and sufficient</u> <u>where</u> <u>seen</u>
Waterways		Breasthooks and Stenson		Pumps <u>Three</u>	
Comings		Transoms, Pointers, and Crutches		Boats <u>Five, (two as life)</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. <u>Good</u>	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>inspection and enquiry</u>	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. / S. 2 1/2</u>	
Topsides		Ceiling		Cables	
Wales	Rudder	Hawsers and Warps			
Plank (Bottom) and Counter	Copper Paint When put on <u>Iron</u>	Standing & Running Rigging			
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>			

She is now in good and efficient condition and fit in my opinion to remain as classed, viz A.1.

Joseph Kellu.

The Amount of Fee.....£ 1 : - : is received by me,

Special.....1 - 1 - 0

Certificate (if required).....

Committee's Minute 4 December 1866

Character assigned A.1.



© 2019

Lloyd's Register Foundation

IRON440-0206