

ANNUAL SURVEYS.

No. 10490 Survey held at Newcastle Date 11th Jan 1864
 on the Ship "Blanton" Master Thos. Wallace
 Tonnage 952 Built at Newcastle When built 1854
 By whom built Marshall & Co Owners Anderson & Co
 Port belonging to Newcastle Destined Voyage Calcutta
 Surveyed Afloat or in Dry Dock Newcastle Dock Company

Last Survey, No. 4357 Port of Newcastle Classed A 1.
9.65

The present Condition of the

Decks	Treenails <u>Painted</u>	Windlass and Capstan <u>Complete</u>
Waterways	Breasthooks and Stemson	Pumps <u>2</u>
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 3/4</u>
Sheerstrakes	Clamps and Shelves	Cables <u>Said to be complete</u>
Topsides	Ceiling	Hawsers and Warps <u>Complete & good</u>
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Painted the paint and oxidation from the surface of the plating. Clean on bottom part of the hull. In a good condition. Re-coated outside with two of oxide of iron and top of Patent paint. Is in good and efficient condition.
 Committee's Minute 12th February 1864
 Character assigned A 1 WMS 1st Class

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____



© 2019

Certificate (if required).

Lloyd's Register Foundation