

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 416 Survey held at London Date 14th to 28th Feby. 18 64.
 on the Iron Ship "Roslin Castle" Master Davidson Prater
 Tonnage 1170 Built at Glasgow When built 1863 (7. Mo.)
 By whom built Napier Owners Currie & Co.
 Port belonging to Glasgow Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock Equal Dry Dock and East India Dock.

Last Survey, No. 4256 Port Iron Classed A. 1. 7/65

REPAIRS

Now done: Scraped and Painted the Bottom with two coats of M^c Linn's Patent Paint, - and the Topsides with Oxide of Iron.

It was stated that the inside of the Bottom plating was fluted when she was built in 1863.

Present Condition of the

Decks	Good	Timberails	Rivets	Windlass and Capstan	
Waterways	Good	Breasthooks and Stemson	Good	Pumps	4 H ^o
Comings		Transoms, Pointers, and Crutches		Boats	5 H ^o
Upper Deck Beams & Fastenings	where	Timbers of the Frame at the openings	where	Masts, Yards, &c.	Good where seen.
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	By enquiry of the Mate.
Planksheers	Painted	Keelsons	seen.	Sails	Good and sufficient
Sheerstrakes		Clamps and Shelves		Anchors	No. of 3 B. 1 S. 2 H.
Topsides	Scraped and painted.	Ceiling	Good where seen.	Cables	where seen.
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper M ^c Linn's Patent Paint When put on	not	Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.			

She is now in good and efficient condition, and fit, in my opinion, to remain as classed A. 1.

The Amount of Fee.....£ is received by me

Special..... 1 : 1 :

Certificate (if required) : 5 :

Committee's Minute 8th March 18 64

Character assigned A. 1.



© 2019

Lloyd's Register Foundation

IRON 440-0379