

5615 Iron
ANNUAL SURVEYS.

28783

No. 11 Survey held at London Date April 3rd 1867
on the Iron S^m "Firefly" Master E. Kenward
Tonnage 502 Built at Liverpool When built 1854
By whom built Owners Gen Iron S^m Co. Comp^y
Port belonging to London Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock Upper Globe dry Dock.

Last Survey, No. 4497 Port of Iron. Classed 6 A. 1. Rest 65.475
(12.65)

the present Condition of the

Decks
Waterways
Rimings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Knees
Strakes
Sides
Rudder
(Bottom) and Counter

Good
where
seen

Treenails Rivets a few Renewed
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper Blacking When put on now

Good
where
seen

Windlass and Capstan
Pumps 2 Main, 3 Bilge.
Boats Two
Masts, Yards, &c. good
Sails
Anchors No. of 3 B. 15.
Cables
Hawsers and Warps
Standing & Running Rigging

Good
and
Sufficient
where
seen

Caulking of Bottom, Deck, and Waterways Good where seen

Renewed a few Rivets, in the bottom, sighted, and
painted it, with one coat of blacking. She is now in good and
efficient Condition fit in our opinion to remain as classed.

Committee's Minute 9th April 18 by
Character assigned Rest 4.1 M.D.

T. S. 1.
Joseph Keen.

Certificate (if required)

No. Survey held at Date 18
on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

the present Condition of the

Decks
Waterways
Rimings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Knees
Strakes
Sides
Rudder
(Bottom) and Counter

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper When put on

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Sails
Anchors No. of
Cables
Hawsers and Warps
Standing & Running Rigging

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18
Character assigned



© 2019

Lloyd's Register
Foundation

Certificate (if required).

IRON 440-0423