

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 376 Survey held at London Date April 29th 18 67
 on the S. John f. Munro Master James Bannister
 Tonnage 612 Built at Sunderland When built 1862
 By whom built Lang Owners Munro & Co
 Port belonging to London Destined Voyage Shanghai via Cardiff
 If Surveyed Afloat or in Dry Dock in Union & St Katharine Docks

Last Survey, No. 2959 Port Ind. Classed 12 A1
11.62

REPAIRS

Lifted lumber boards and ceiling in flat to above bilges;
 repaired cement and painted inside surfaces of plating from
 lower deck stringer down to cement; scraped, and painted
 bottom with two coats of Zinc paint and one of tallow.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B, 1 S, 2 K</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>✓</u> When put on <u>✓</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where seen Good</u>	

Is now in good and efficient condition and in my opinion eligible to
 be classed A1 the same being desired by the Owner, and marked
 S.S. No. 1. 67.

The Amount of Fee.....£ — : — : is received by me. John Maxwell
 Special..... / : / : 0 ✓
 Certificate (if required) : :

Committee's Minute 7th May 18 67
 Character assigned A1



© 2019

Lloyd's Register
 Foundation

ICON440-0472