

Iron 5387
ANNUAL SURVEYS.

No. 56 Survey held at London Date 18th June 18 67
on the Iron Ship "Tantallon Castle" Master William Pole
Tonnage 1037 Built at Greenock When built 1885 (3 Mo.)
By whom built Steel Owners Currie & Co.
Port belonging to Liverpool Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Wilframs' dry dock and East India dock.

Last Survey, No. 5092 Port of Mon. Classed A. 1.
9.66

The present Condition of the

Decks	<u>Good</u>	Keels	<u>Good</u>	Windlass and Capstan	
Waterways		Breasthooks and Stemson	<u>Good</u>	Pumps	<u>2 No.</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>5 No.</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	<u>and</u>
Lower Deck Beams & Fastenings	<u>where</u>	Ditto ditto at other places		Sails	
Planksheers		Keelsons	<u>where</u>	Anchors	No. of <u>3 B. 15. 2 K.</u> <u>sufficient</u>
Sheerstrakes		Clamps and Shelves		Cables	<u>where</u>
Topsides		Ceiling	<u>seen</u>	Hawsers and Warps	<u>seen</u>
Wales	<u>seen</u>	Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	<u>scraped and painted</u>	Copper	<u>Paint</u> When put on <u>Nov. 1885</u>		
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways	<u>Good where seen</u>		

Scraped and painted the Bottom. - She is in good and efficient condition, and fit, in my opinion, to remain classed: - A. 1.

Committee's Minute 25th June 18 67

Character assigned A. 1

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18 ____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors
Sheerstrakes	Clamps and Shelves	No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	Standing & Running Rigging
General Observations and Opinion,	When put on	
	Caulking of Bottom, Deck, and Waterways	

Committee's Minute _____ 18 ____

Character assigned _____



© 2019

Lloyd's Register

Certificate (if required).

IRON 441-0048