

ANNUAL SURVEYS.

5622

28784

No. 100 Survey held at London Date July 31st 18 67
 on the S " Bebington " Master Warland
 Tonnage 889 Built at Belfast When built 1859
 By whom built Hickson Owners R. Hickson
 Port belonging to Liverpool Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock in Bridge & East India Dock

Last Survey, No. 478 Port of Iron Classed A1
4728 S.S. No. 2.66 F. 66

The present Condition of the
 Decks where seen Good Treenails Rivets where seen Good Windlass and Capstan Good
 Waterways " " " " Breasthooks and Stemson " " " " Pumps " " " "
 Comings " " " " Transoms, Pointers, and Crutches " " " " Boats " " " "
 Upper Deck Beams & Fastenings " " " " Timbers of the Frame at the Openings " " " " Masts, Yards, &c. " " " "
 Lower Deck Beams & Fastenings " " " " Ditto ditto at other places " " " " Sails " " " "
 Planksheers " " " " Keelsons " " " " Anchors No. of 3 B, 1 S, 2 K
 Sheerstrakes " " " " Clamps and Shelves " " " " Cables " " " "
 Topsides " " " " Ceiling " " " " Hawser and Warps " " " "
 Wales " " " " Rudder " " " " Standing & Running Rigging " " " "
 Plank (Bottom) and Counter " " " " Copper ✓ When put on ✓

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good
Scraped bottom and painted with two coats of Mc Innes's patent paint.
Is now in good and efficient condition and in my opinion eligible to remain
as classed.

Committee's Minute 9th August 18 67
 Character assigned A1 M.A.S.

John Maxwell

Certificate (if required).

No. 101 Survey held at London Date August 5th 18 67
 on the S " Khandeish " Master Storey
 Tonnage 1004 Built at Port Glasgow When built 1864
 By whom built Duncan Owners Iron Ship Co
 Port belonging to Bombay Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock in Pontoons Victoria dock & East India Dock

Last Survey, No. 4533 Port of Iron Classed A1
66

The present Condition of the
 Decks where seen Good Treenails Rivets where seen Good Windlass and Capstan Good
 Waterways " " " " Breasthooks and Stemson " " " " Pumps " " " "
 Comings " " " " Transoms, Pointers, and Crutches " " " " Boats " " " "
 Upper Deck Beams & Fastenings " " " " Timbers of the Frame at the Openings " " " " Masts, Yards, &c. " " " "
 Lower Deck Beams & Fastenings " " " " Ditto ditto at other places " " " " Sails " " " "
 Planksheers " " " " Keelsons " " " " Anchors No. of 3 B, 1 S, 2 K
 Sheerstrakes " " " " Clamps and Shelves " " " " Cables " " " "
 Topsides " " " " Ceiling " " " " Hawser and Warps " " " "
 Wales " " " " Rudder " " " " Standing & Running Rigging " " " "
 Plank (Bottom) and Counter " " " " Copper ✓ When put on ✓

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good
Painted bottom with composition paint.
Is now in good and efficient condition and in my opinion eligible to
remain as classed.

Committee's Minute 9th August 18 67
 Character assigned A1 M.A.S.

John Maxwell

Certificate (if required).