

5633

28530

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 155 Survey held at London Date Aug 6th 12 1867
 on the Iron Screw "Despatch" Master G. Morrell
 Tonnage 7562 Built at Newcastle When built 1863
 By whom built Palmer Owners R. Forey
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Limetree (Dry Dock)

Last Survey, No. 5104 Port Iron. Classed TC. 1.
 (S.S. No. 66)
 9, 66

REPAIRS

now done,

The bottom scraped and painted with Red-lead -

Present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} _____
Waterways		Breasthooks and Stemson		Pumps	
Comings	} _____	Transoms, Pointers, and Crutches	} _____	Boats	} <u>good</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto Ditto at other places	} <u>where</u>	Condition, how ascertained	} <u>where</u>
Planksheers	} <u>painted</u>	Keelsons	} _____	Sails	} _____
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. 15 2 1/2</u>	
Topsides	} <u>seen</u>	Ceiling	} <u>seen</u>	Cables	} <u>seen</u>
Wales	} _____	Rudder	} _____	Hawsers and Warps	} _____
Plank (Bottom) and Counter	} _____	Copper Paint When put on	} <u>now</u>	Standing & Running Rigging	} _____

General Observations and Opinion, _____
 Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good condition fit in my opinion to remain as classed

The Amount of Fee.....£ — : — : is received by me,
 Special..... — : — :
 Certificate (if required) : :

G. Morrell

Committee's Minute 2nd August 1867
 Character assigned TC. 1.



© 2019
 Lloyd's Register Foundation