

REPORT of SURVEY for REPAIRS.

in book. No. 5048 Survey held at London Date July 31st 1867
 on the S. "Pandora" (Iron) Master Edmund Ankers
 Tonnage 1156 Built at Glasgow When built 1864
 By whom built Moore & Co Owners Moore & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Pontoon & Victoria Dock

Last Survey, No. 5048 Port Iron Classed A 1
 9.66

REPAIRS

Bottom scraped, about six butts on each side recaulked and the bottom repainted with two coats of Zinc and Red Lead and one coat of Tallow—

The battens taken down in the hold and the inside thoroughly painted one hatch of ceiling lifted and the cement found in good condition

Present Condition of the

Decks		Trunnels	Rivets	Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	Good	Ditto Ditto at other places	Good	Condition, how ascertained	Good and
Planksheers		Keelsons		Sails	
Sheerstrakes	where seen	Clamps and Shelves	where seen	Anchors No. of	sufficient
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper	When put on	Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is eligible in my opinion to remain as classed A 1

The Amount of Fee.....£ — : — : } is received by me.

Special..... 1 : 1 : }

Certificate (if required) : : }

Committee's Minute 13th August 1867

Character assigned A 1 Mas.



© 2019

Lloyd's Register Foundation

IRON44-0122