

5682

REPORT of SURVEY for REPAIRS.

Dec 17/12/66

No. in Reg. Book. **No. 1848** Survey held at **Belfast** Date **10th December** 18**66**
91 on the **Iron Screw Steamer "De Brus"** Master **John Wright**
Tonnage **261** Built at **Middlesbro** When built **1858**
By whom built _____ Owners **Miron**
Port belonging to **Wakefield** Destined Voyage **Coaster**
If Surveyed Afloat or in Dry Dock **Afloat**

Last Survey, No. **5681** Port **Iron** Classed **9 A1. (7564)**
4.64

REPAIRS

This vessel was in collision with the ship "Lahore", at the entrance of this Harbour, while on her passage from Green, Stenison, Nosspit, and part of the topgallant fore Castle deck, broken. Upper edge of sheerstrake on both sides forward bent, and partly broken

She was temporarily repaired here, and left this on the 10th instant for Glasgow.

Alex Linton

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained,
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

The Amount of Fee.....£ : : is received by me,
Special..... : :
Certificate (if required) : :

Committee's Minute **18th December 1866**

Character assigned **On Clyde No 2678**

IRON 44-0143



Refered
to Lloyd's Register
L. 18/12/66
Lloyd's Register
Foundation