

# ANNUAL SURVEYS.

No. 202 on the S.S. "Hector" Survey held at London Date Sept 6<sup>th</sup> 18 67  
 Tonnage 1614 Built at                      When built 1863  
 By whom built 1285 Jain Owners Gowley  
 Port belonging to Sunderland Destined Voyage                       
 If Surveyed Afloat or in Dry Dock on Pontoons Victoria Dock

Last Survey, No. 5146 Port of Iron E.S. 65 Classed GA1  
Spar Decked 12.65 10.66

The present Condition of the

Decks <u>where seen Good</u>	Treenails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>                    </u>	Breasthooks and Stemson <u>                    </u>	Pumps <u>                    </u>
Comings <u>                    </u>	Transoms, Pointers, and Crutches <u>                    </u>	Boats <u>                    </u>
Upper Deck Beams & Fastenings <u>                    </u>	Timbers of the Frame at the Openings <u>                    </u>	Masts, Yards, &c. <u>                    </u>
Lower Deck Beams & Fastenings <u>                    </u>	Ditto ditto at other places <u>                    </u>	Sails <u>                    </u>
Planksheers <u>                    </u>	Keelsons <u>                    </u>	Anchors No. of <u>3 B, 1 S. 2 K.</u>
Sheerstrakes <u>                    </u>	Clamps and Shelves <u>                    </u>	Cables <u>                    </u>
Topsides <u>                    </u>	Ceiling <u>                    </u>	Hawsers and Warps <u>                    </u>
Wales <u>                    </u>	Rudder <u>                    </u>	Standing & Running Rigging <u>                    </u>
Plank (Bottom) and Counter <u>                    </u>	Copper <u>                    </u> When put on <u>                    </u>	

General Observations and Opinion, .

Caulking of Bottom, Deck, and Waterways where seen Good

Scraped and painted bottom with two coats of red and white lead paint.  
 Is now in good and efficient condition and in my opinion eligible  
 to remain as classed.

Committee's Minute 14<sup>th</sup> September 1867

Character assigned GA1 M.S.

*John Maxwell*

Certificate (if required)

No.                      Survey held at                      Date                      18                       
 on the                      Master                       
 Tonnage                      Built at                      When built                       
 By whom built                      Owners                       
 Port belonging to                      Destined Voyage                       
 If Surveyed Afloat or in Dry Dock                     

Last Survey, No.                      Port of                      Classed                     

The present Condition of the

Decks <u>                    </u>	Treenails <u>                    </u>	Windlass and Capstan <u>                    </u>
Waterways <u>                    </u>	Breasthooks and Stemson <u>                    </u>	Pumps <u>                    </u>
Comings <u>                    </u>	Transoms, Pointers, and Crutches <u>                    </u>	Boats <u>                    </u>
Upper Deck Beams & Fastenings <u>                    </u>	Timbers of the Frame at the Openings <u>                    </u>	Masts, Yards, &c. <u>                    </u>
Lower Deck Beams & Fastenings <u>                    </u>	Ditto ditto at other places <u>                    </u>	Sails <u>                    </u>
Planksheers <u>                    </u>	Keelsons <u>                    </u>	Anchors No. of <u>                    </u>
Sheerstrakes <u>                    </u>	Clamps and Shelves <u>                    </u>	Cables <u>                    </u>
Topsides <u>                    </u>	Ceiling <u>                    </u>	Hawsers and Warps <u>                    </u>
Wales <u>                    </u>	Rudder <u>                    </u>	Standing & Running Rigging <u>                    </u>
Plank (Bottom) and Counter <u>                    </u>	Copper <u>                    </u> When put on <u>                    </u>	

General Observations and Opinion, .

Caulking of Bottom, Deck, and Waterways                     

Committee's Minute                      18

Character assigned                     



© 2019

Lloyd's Register  
 Foundation

Certificate (if required).

IRON44-0172