

# ANNUAL SURVEYS.

No. 20854 Survey held at Liverpool Date 5<sup>th</sup> & 19<sup>th</sup> Sept. 1867  
 on the Iron Ship Artist Master Sergeant  
 Tonnage 1371 Built at Hull When built 1864 12 mo  
 By whom built \_\_\_\_\_ Owners Harrison  
 Port belonging to Liverpool Destined Voyage for India  
 If Surveyed Afloat or in Dry Dock Carence Gearing and Andrew Asks

Last Survey, No. 20183 5111 Port of Liverpool

Classed A1 10.66

The present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>Good</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>Where</u>	Ditto ditto at other places _____	Sails <u>Supp</u>
Planksheers _____	Keelsons <u>Where</u>	Anchors No. of <u>3/3 15 24</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables <u>38 7 fashions</u> <u>Where</u>
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging <u>Seen</u>
Plank (Bottom) and Counter <u>Seen</u>	Copper <u>Cemented</u> When put on <u>When built</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good Where Seen

Respectfully referring to Liverpool report No 20183. and the Owners letter appended thereto. the chain cables in question have now been ranged on deck and found to accord in length, diameter and test marks. with the certificates produced at that time. She is now in good and efficient condition capable to remain as

Committee's Minute Liverpool 24<sup>th</sup> Sept 1867 classed A1

Character assigned A1 - Can 64

7.9.2.

Certificate (if required)

No. \_\_\_\_\_ Survey held at Liverpool Date 5<sup>th</sup> Sept 1867  
 on the Iron S. "Antiope" Master Withers  
 Tonnage 1443 Built at Port Glasgow When built 1866-8 mo  
 By whom built Reis Owners Heap & Co  
 Port belonging to Liverpool Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Queens dry dock

Last Survey, No. 5060 Port of Iron.

Classed A1 66

The present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>Good</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>Where</u>	Ditto ditto at other places _____	Sails <u>Where</u>
Planksheers _____	Keelsons <u>Where</u>	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling <u>Seen</u>	Hawsers and Warps <u>Seen</u>
Wales <u>Seen</u>	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper <u>Cemented</u> When put on <u>When built</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Bottom cleaned & treated. new main top gallant mast she appears in good condition and in my opinion may continue as classed

Committee's Minute Liverpool 24<sup>th</sup> Sept 1867

Character assigned A1 - Can 66

7.9.2.

Certificate (if required).



LLOYD'S REGISTER

"Artist"  
-208544  
"Antipac"



© 2019

Lloyd's Register  
Foundation