

3308 2013-4324-5079
5982

28716

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 423 Survey held at London Date Nov^r 11th 18 67
on the S.S. "John McIntyre" Master J. Douglas
Tonnage 985 Built at Newcastle When built 1863
By whom built Palmer Owners Jory & Son
Port belonging to London Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock on Pontons Victoria Dock

Last Survey, No. 5079 Port Iron. Classed A1
8-66

REPAIRS

Lifted ceiling at bilges and took off man hole doors ^{of tanks} for the inspection of frames asphalt &c all of which were found to be in good condition and the asphalt adhering in a satisfactory manner. Scraped and painted bottom with two coats of red and white lead and one of tallow.

Present Condition of the		
Decks <u>where seen</u> <u>Good</u>	Treenails <u>Rivets where seen</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from engine &c &c from deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B, 1 S, 2 K.</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>✓</u> When put on <u>✓</u>	Standing & Running Rigging
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>where seen</u> <u>Good</u>

Is now in good and efficient condition and in my opinion eligible to be marked S.S. No 1. by

The Amount of Fee.....£ : : is received by me,
Special..... 1 : 1 : 0
Certificate (if required) : :

Committee's Minute 25th January 18 68

Character assigned A1
S.S. McIntyre WMS

Thos Maxwell



© 2019

Lloyd's Register Foundation

IRON44-0434