

6072
Iron

29023

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 117 Survey held at London Date March 2nd 18 68
 on the S.S. Hastings Master Edward Harvey
 Tonnage 696 Built at North Shields When built 1864
 By whom built 535 Smith Owners Harris & Co
 Port belonging to London Destined Voyage Black Sea
 If Surveyed Afloat or in Dry Dock on Pontons afloat Victoria Dock

Last Survey, No. 1479 Port London Classed B1
12.65

REPAIRS

Lifted ceiling at bilges equal to a strake and took off all man hole doors for the thorough examination of floor plates, frames, plating, cement &c all of which were found to be in good condition the cement adhering in a satisfactory manner; took up lining upon water ballast tank and scraped and painted the upper part of tank; scraped and painted bottom with three coats of composition paint, Renewed foremast, and repaired mizzen

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B, 1 S, 2 R</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>✓</u> When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where seen Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed and be marked S. S. No. 1. 68

The Amount of Fee.....£ : : is received by me. Edw. Harvey
 Special..... 1 : 1 : 0
 Certificate (if required) : 5 :

Committee's Minute 11th March 18 68

Character assigned B1
S. S. No. 1-68 MMS



© 2019

Lloyd's Register Foundation

IRON442-G042