

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 57 Survey held at London Date March 21st to 26th April 1868.
 on the Iron Ship "Santallow Castle" Master J. Thomson
 Tonnage 1057 built at Greenock When built 1865. (3 mo.)
 By whom built Steel Owners Currie and Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Wigram's dry Dock, and East India Dock.
 Last Survey, No. 5587 Port Iron. Classed A.1. (9.66.)
 REPAIRS Now done.

Sighted bottom, scraped, and payed with two coats of brown, and one of Mc Almes's Patent composition; the topsides scraped and painted.

Repaired head rails, and timbers; lifted some hatches in the fore and after ends of the hold, and found the frames, floor-plates, &c., and the Cement in good condition

Present Condition of the

Decks	Wrecks	Rivets	Windlass and Capstan
Waterways	Breasthooks and Stemson		Pumps <u>2 in and 1 fore</u>
Comings	Transoms, Pointers, and Crutches		Boats <u>5</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings		Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places		Condition, how ascertained <u>insp^{2d} and evening</u>
Planksheers	Keelsons		Sails
Sheerstrakes	Clamps and Shelves		Anchors No. of <u>3 B. 1 C. 2 H.</u>
Topsides	Ceiling		Cables
Wales	Rudder <u>the good</u>		Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Paint</u> When put on <u>now</u>		Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen.</u>		

She is now in good and efficient condition and fit in my opinion to remain as Classed Viz

The Amount of Fee.....£ : : is received by me,

Special..... : : :

Certificate (if required) : : :

Committee's Minute 7th April 18 68

Character assigned A.1. M



© 2019

Lloyd's Register Foundation

IRON442-0108