

6159
Iron Ship.

29098

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 413 No. 5641 Survey held at London Date Mar 19th to 25th 1868
on the Iron S.S. "Greatham Hall" Master T. Waite
Tonnage 583 Built at Stockton When built 1857
By whom built _____ Owners Pearse & Co
Port belonging to W. Hartlepool Destined Voyage Lisbon
If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 5641 Port Iron Classed B. 1
REPAIRS now done, SS. No 3. 66

The bottom scraped and painted with Coal Tar, Black-lead & Arsenic; the upper deck caulked; and the Engine & Boilers overhauled and repaired -

Present Condition of the

Decks	good	Freonails	Rivets	good	Windlass and Capstan	good
Waterways		Breasthooks and Stemson			Pumps	where
Comings		Transoms, Pointers, and Crutches			Boats	four
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings			Masts, Yards, &c.	seen
Lower Deck Beams & Fastenings	where	Ditto Ditto at other places	where		Condition, how ascertained	from deck
Planksheers	painted	Keelsons			Sails	good
Sheerstrakes	"	Clamps and Shelves			Anchors	No. of 3 B. 1 S 2 R
Topsides	"	Ceiling	seen		Cables	2
Wales	4	Rudder			Hawsers and Warps	sufficient
Plank (Bottom) and Counter	painted	Copper Paint	When put on	now	Standing & Running Rigging	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good and efficient condition, fit in my opinion to remain as classed B. 1.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 7th April 18 68

Character assigned B. 1 ams



© 2019

Lloyd's Register Foundation

IRON442-0130