

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 46 Survey held at London Date Feb 11th 18 68
 on the S.S. Achilles (Iron) Master W. Ritchie
 Tonnage 781 Built at Sunderland When built 1865
 By whom built _____ Owners Gowley &
 Port belonging to Sunderland Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Buttman's Dock & Victoria Dock

Last Survey, No. 5184 Port Iron Classed B 1
 11, 66

REPAIRS

The ceiling of this vessel has now been lifted in accordance with Survey No 1.
 The cement in the fore and after holds has now been renewed and also where practicable in the Engine Room.

Present Condition of the

Decks	Freemasts <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

This vessel is now in good condition and is eligible in our opinion to remain classed and to be marked (S.S. No 1)

The Amount of Fee.....£ : : is received by me,

Special..... 1: 1: -

Certificate (if required) : 5: -

Committee's Minute 8th May 18 68

Character assigned B 1

(S.S. No. 138) G.M.S.

Thos. W. Hawn

Joseph Allen

Lloyd's Register Foundation

IRON 442-0170