

6226

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date Feb<sup>r</sup> 20<sup>th</sup> 21<sup>th</sup> 18 67  
 on the Iron Screw Ste<sup>r</sup>. Cromwell Master Robt<sup>r</sup> Howe  
 Tonnage 554 438 Built at Glasgow When built 1865.  
 By whom built E & S. Company Owners Gen<sup>l</sup>. Iron Screw Collier Company.  
 Port belonging to London Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Up<sup>r</sup> Globe dry dock and afloat near the dock

Last Survey, No. 5147 Port Iron. Classed A. 1.

## REPAIRS

chiefly from damage. The New Mizzen, mast now put in, and new chain plates on the starb<sup>d</sup> side to the Mizzen rigging. New Mizzen Schmain. Chalk'd part deck and Comings at the after part of Vessel. Clean'd the bottom overhauled the butts of plates. Recoated the bottom with black Varnish. —

### Present Condition of the

Decks <u>in good order</u>	Treenails <u>Rivets where seen</u> <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>firm</u> <u>"</u>	<del>Timbers</del> of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>new mizen &amp; top</u> <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>from the deck &amp; "</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u> <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>9</u>
Wales <u>"</u>	Rudder <u>efficient</u> <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>When put on</u>	Standing & Running Rigging <u>"</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good

I am of opinion this Vessel is entitled to remain as Class'd A. 1.  
 Samuel Presious.

The Amount of Fee.....£ : : } is received by me,  
 Special..... / : / : }  
 Certificate (if required) : : }

Committee's Minute 18

Character assigned



© 2019

Lloyd's Register  
Foundation

IRON 442-0195