

6291.

24354

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 141 Survey held at London Date June 2<sup>nd</sup> 1868  
on the S.S. "Onward" Master Priest  
Tonnage 623 built at Sunderland When built 1865  
By whom built \_\_\_\_\_ Owners Priest Bros  
Port belonging to Hull Destined Voyage Cardiff  
If Surveyed Afloat or in Dry Dock Millwall docks

Last Survey, No. 5890 Port Iron Classed B 1  
11.67

REPAIRS  
In consequence of damage, Windlass repaired -  
decks also and engine room comings, one deck beam  
scarphed where broken, several bufts recaulked and  
slack rivets renewed - two plates on port bow renewed,  
steering apparatus renewed, Bulwark stantions refitted  
& Decky recaulked -

Present Condition of the		
Decks	Transoms	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging

General Observations and Opinion, good  
Caulking of Bottom, Deck, & Waterways. good  
This vessel is elegible in my opinion  
to remain as classed B 1

The Amount of Fee.....£ 2 : — : — is received by me,  
Special damage. 3 : 3 : —  
Certificate (if required) 5/-  
Thos. McTearna

Committee's Minute 16<sup>th</sup> June 1868

Character assigned B 1  
record damage upon