

ANNUAL SURVEYS.

No. 24348 Survey held at Birkenhead and Liverpool Date June 18th to July 4th 1868.
on the Iron Ship "Orient" Master Stamilton
Tonnage 972 Built at Birkenhead When built 1861 - 10th
By whom built Laird Owners Clint & Co.
Port belonging to Liverpool Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Laird Birkenhead Dry Dock and afloat.

Last Survey, No. 5365 Port of Iron.

Classed AL.
S.S. nos - 64 67

the present Condition of the

cks	
aterways	"
omings	"
per Deck Beams & Fastenings	Iron
ver Deck Beams & Fastenings	Good
unksheers	where
erstrakes	seen
sides	
les	
nk (Bottom) and Counter	Painted

Treenails _____
Breasthooks and Stemson _____
Transoms, Pointers, and Crutches _____
Timbers of the Frame at the Openings *Iron*
Ditto ditto at other places *good*
Keelsons *When*
Clamps and Shelves *seen*
Ceiling _____
Rudder _____
Copper *Cement* in When put on *1861*.

Windlass and Capstan good
Pumps "
Boats good and sufficient
Masts, Yards, &c. "
Sails good and complete
Anchors No. of 3 B. 1 S. 2 H.
Cables good where seen
Hawsers and Warps "
Standing & Running Rigging "

eral Observations and Opinion,

add on
Caulking of Bottom, Deck, and Waterways

now done. Hatchets lifted in the flat of bottom all gone & aft. Cement repaired
the floors Cement washed, Chain plates repaired where found worn and the bottom
venish scraped and painted. The Owner intends having the plating above the bilges and
the inside scraped and painted during the time of her being at Calcutta with a view to
S. S. on her return. - She is now in my opinion eligible to remain as Classed A1.

Committee's Minute

Character assigned

Certificate (if required).

No. 204 Survey held at Liverpool Date 17th to 20th June 1868
on the iron screw steamer "Gladiator" Master J. Reynolds
Tonnage 591 Built at Stockton When built 1860 - 9 mo
By whom built Parpe Owners J. & J. Harrison
Port belonging to Liverpool Destined Voyage Pernambuco
If Surveyed Afloat or in Dry Dock Mercurianum Drying Dock

Last Survey, No. 5065 Port of Iron.

Classed 9.11
29.65 9.0

Present Condition of the

ways _____

gs _____

Deck Beams & Fastenings _____

Deck Beams & Fastenings _____

sheers _____

strakes _____

ides _____

s _____

sk (Bottom) and Counter _____

Handwritten notes:

- Work* (written vertically on the right side)
- Phone down* (written diagonally across the bottom right)

Treenails *Nails*
 Breasthooks and Stems _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Ditto ditto at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Copper *Lead* When put on *100*

Windlass and Capstan 2006
Pumps
Boats
Masts, Yards, &c.
Sails
Anchors No. of
Cables
Hawsers and Warps
Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with M^cIntiss Composition.
Is now in good and efficient condition and in my opinion
eligible to remain as is. Passed G.A.

Committee's Minutes

Character assigned

Certificate (if required).

IRON 442-0327

"Orient"
—21.348—
"Gladiator"



© 2019

Lloyd's Register
Foundation