

# REPORT of SURVEY for REPAIRS.

in Book. No. 6432 Survey held at London Date August 11<sup>th</sup> 18 68  
 on the Sh. Kate Gatham Master Hitchins  
 Tonnage 275 built at Greenock When built 1863  
 By whom built Steele Owners J. R. Gatham  
 Port belonging to London Destined Voyage Port Natal  
 If Surveyed Afloat or in Dry Dock in Union & St Katharine Dock  
 Last Survey, No. 5392 Port Iron Classed A1  
S.S. No. 1. 67. 3.67

Scraped and painted bottom with two coats of oxide of iron, two  
 of zinc paint and one of tallow

Renewed one plate of topsides on Starboard side in conse-  
 quence of defect.

Condition of the

Where seen <u>Good</u>	Treenails <u>Rivets Where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Decks	Transoms, Pointers, and Crutches	Boats
Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from enquiry &amp; as seen from deck</u>
Decks	Keelsons	Sails
Decks	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 2 H.</u>
Decks	Ceiling	Cables
Decks	Rudder	Hawsers and Warps
(Bottom) and Counter	Copper <u>When put on</u>	Standing & Running Rigging
Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Where seen Good</u>	

Is now in good and efficient condition and in my opinion eligible  
 to remain as classed.

Amount of Fee.....£ : 10 : is received by me, John Maxwell  
 Special..... : 1 :  
 Certificate (if required) : 5 :  
 Committee's Minute 18<sup>th</sup> August 18 68  
 Officer assigned B. 1 MAS



© 2019

Lloyd's Register  
Foundation

IRON442-0398