

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *429* No. *21427* Survey held at *Liverpool* Date *16th Sept. 1867*  
 on the *Iron Ship "Allahabad"* Master *R. Burnett*  
 Tonnage *1176* Built at *Liverpool* When built *1864*  
 By whom built *Cutter* Owners *Thos. Stephens*  
 Port belonging to *London* Destined Voyage *Bombay*  
 If Surveyed Afloat or in Dry Dock *Herculean Graving Dock and afloat*

Last Survey, No. *4569* Port *Iron.* Classed *A1* *Chartered*

## REPAIRS

*Inside from bilges upwards including beams &c.  
 cleaned and painted bottom coated with paint and  
 tallow.*

### Present Condition of the

Decks	<i>where seen</i>	Treenails <i>where seen</i>	Windlass and Capstan <i>Good</i>
Waterways		Breasthooks and Stems	Pumps <i>Good</i>
Comings		Transoms, Pointers, and Crutches	Boats <i>Good</i>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	Masts, Yards, &c. <i>Good</i>
Lower Deck Beams & Fastenings		<i>Ditto</i> <i>Ditto</i> at other places	Condition, how ascertained <i>seen from the deck</i>
Planksheers		Keelsons	Sails <i>Good</i>
Sheerstrakes		Clamps and Shetfs	Anchors No. of <i>2</i>
Topsides		Ceiling	Cables <i>and</i>
Wales		Rudder	Hawsers and Warps <i>sufficient</i>
Plank (Bottom) and Counter		Copper <i>on</i> When put on <i>1864</i>	Standing & Running Rigging
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <i>where seen</i>	

*Is now in good and efficient condition and in  
 my opinion eligible to remain as Classed A1.*

The Amount of Fee.....£ / : : is received by me,

Special..... / : : — *5/1868*

Certificate (if required) : 5 :

Committee's Minute *Liverpool 1st September 1868*

Character assigned *A1. Need change of name*

*(Can. 64)*

*J. S. M.*



© 2019

Lloyd's Register  
 Foundation

IRON442-0424



Allahabad  
- 21427 -



© 2019

Lloyd's Register  
Foundation

RECORD OF SURVEY FOR 1842