

6491  
row -

29374

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 118 Survey held at Londow Date 5<sup>th</sup> August 1868.  
 on the Iron Screw "Samuel Laing" Master J. Bradley  
 Tonnage 606 built at Newcastle When built 1874.  
 By whom built Palmer Owners Taylor & Co.  
 Port belonging to Londow Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Pontoon Victoria dock.

Last Survey, No. 3527 Port Iron Classed 6. font. 3 yrs.  
 (Z.S. 1863)  
 PAIRS Clap omitted 5/63

Sighted the Bottom. - wrote to the Ship's husband pointing out what would be required to reclass this vessel; received the accompanying reply deching survey.

W. Williamson.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

The Amount of Fee.....£ : : is received by me,  
 Special..... : :  
 Certificate (if required) : :

Committee's Minute 11<sup>th</sup> August 1868.

Character assigned Refused



© 2019  
 Lloyd's Register  
 Foundation  
 IRON442-0457