

6536

REPORT of SURVEY for REPAIRS.*Change of Owners.**Run 16/3/68*No. in
Reg. Book.
488No. *2145*

Survey held at

Liverpool

Date

*August 26*18 *68*on the *Iron Ship**"Hyderabad"*

Master

*Jones*Tonnage *1339*

Built at

Port Glasgow

When built

1865 - 5 m^e

By whom built

Duncan

Owners

Jas Baines Taylor & Co

Port belonging to

Liverpool

Destined Voyage

Melbourne

If Surveyed Afloat or in Dry Dock

Queen's Quay Afloat & afloat

Last Survey, No.

5128

Port

Iron.

Classed

*A1.**66*

REPAIRS

*now done.**Bottom painted.*

Present Condition of the

Decks

good

Waterways

"

Comings

"

Upper Deck Beams & Fastenings

Iron

Lower Deck Beams & Fastenings

good

Planksheers

where

Sheerstrakes

seen

Topsides

Wales

Hulk (Bottom) and Counter

painted

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Iron

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Cement When put on

when built

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Now found in good condition, and in my opinion eligible to remain as Classed A1.

The Amount of Fee.....£ 1 : " : " is received by me,

Special.....

Certificate (if required)

Committee's Minute

Liverpool, 15th September 1868

Character assigned

*A1**Record Change of Name
Cm-65.**J. F. Light.*

© 2019

Lloyd's Register
Foundation
IRON 443-0006

REPORT OF THE SECRETARY FOR REPAIRS

Hydrabad
21.4.51



© 2019

Lloyd's Register
Foundation