

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No. *4463*

Survey held at

Liverpool

Date

15th to 17th Sept 1868

on the

TB^h Warrior

Master

W. A. B.

Tonnage

490

built at

Stockton

When built

1858

By whom built

Owners

Tennant

Port belonging to

Liverpool

Destined Voyage

W. A. B.

If Surveyed Afloat or in Dry Dock

Cunningham's Dock

Last Survey, No.

4279

Port

Iron.

Classed

12 A 1

REPAIRS

25. 66.

8. 65.

No timbers and three separate strakes of ceiling between the keel and keelson on each side removed the cement and the iron where exposed found good the bottom outside cleaned and coated

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

This vessel is now in good and efficient condition - eligible to remain as classed: or with the approval of the Committee to be classed A 1 and noted S.S. No. 2. 68

The Amount of Fee.....£ - : - : - is received by me.

Special..... 2 : 2 : - 23/9/68

Certificate (if required) : 5 :

Committee's Minute *Liverpool 25th September 1868*

Character assigned *A 1* S.S. No. 2-68

J. S. M.



© 2019

Lloyd's Register Foundation

IRON443-0028

REPORT OF SURVEY OF THE HARBOR



Warrior
21462



© 2019
Lloyd's Register
Foundation