

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 2657** Survey held at Liverpool Date Oct 9 to Nov 14 1868
 on the Iron S. Weathersfield Master A Morris
 Tonnage 1051 built at P Glasgow When built 1865-2 mo
 By whom built Funcan Owners Lowie & Co
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Flavence Graving & Prince's dock

Last Survey, No. 5867 Port Iron. Classed A-1. 11-67
 REPAIRS now done

Nearly all the Ceiling in flat of bottom & plating - both sides fore & aft - taken up; all oxidation removed, found the surfaces of plating & the rivetting in good condition & have now been coated with Composition & other paint where required.

Present Condition of the

Decks	<u>Good</u>	Freeboards	<u>Pilots - Good</u>	Windlass and Capstan	<u>Good & sufficient</u>
Waterways	"	Breasthooks and Stemson		Pumps	"
Comings	"	Transoms, Pointers, and Crutches		Boats	<u>Four</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		Condition, how ascertained	<u>Seen from deck</u>
Planksheers	"	Keelsons	"	Sails	<u>Good & sufficient</u>
Sheerstrakes	"	Clamps and Shelves		Anchors	No. of <u>3 B's - 1 S & 2 H's</u>
Topsides	"	Ceiling	"	Cables	<u>Good where seen</u>
Wales	"	Rudder	"	Hawsers and Warps	<u>Good & sufficient</u>
Plating (Bottom) and Counter	"	Cement <u>good</u>	When put on <u>then built</u>	Standing & Running Rigging	"

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Satisfactory

I now in an efficient condition & in my opinion eligible to remain as Classed, & marked S.S. No. 1 - 1868

The Amount of Fee.....£ - : - : is received by me,

Special..... 3 : 3 : " 5/100 RM

Certificate (if required) " : 5 : "

Committee's Minute Liverpool 8th January 1869

Character assigned A-1 - 18.5.70.68

Com-65



© 2019

Lloyd's Register Foundation

IRON 443-0258

Veathersfield
-21657-